



**NOTES**

- 1 ALL SEAT LOCATION DIMENSIONS ARE MEASURED TO CENTRELINE OF FWD SEAT LEG STUD.
- 2 SEAT INSTALLATION TO BE CARRIED OUT IN CONJUNCTION WITH SAI MODIFICATION B737-MOD-0022.
- 3 SEAT PITCHES ARE SYMMETRICAL ABOUT THE AIRCRAFT CENTRE LINE UNLESS SHOWN OTHERWISE.
- 4 SEAT COVERINGS AND FOAMS MUST MEET FLAMMABILITY REQUIREMENTS OF CS25.853.
- 5 SEATS AT ROW 6 TO HAVE RECLINE FULLY DISABLED AND LOCKED IN THE FULLY UPRIGHT POSITION.
- 6 SEATS AT ROW 7 TO HAVE FOOTREST FUNCTION RESTRICTED SUCH THAT IT DOES NOT EXTEND BEYOND CENTRELINE OF TYPE III EXIT (STA627.5). REF CAP747 GR No. 3 FOR GUIDANCE.
- 7 INSTALL REPLACEMENT SEAT TRACK INFILL STRIPS, WHERE REQUIRED.
- 8 RE-POSITION SEAT ROW NUMBER DECALS IN OVERHEAD BIN STRIP TO SUIT.
- 9 PLACARD PASSENGER SEAT LOCATIONS AS REQUIRED TO ACCOMODATE 56 PAX.
- 10 RELOCATE EXISTING PSU PANELS TO PROVIDE A SPEAKER AND NS/FSB SIGN AT THE BEGINNING OF EVERY SEAT ROW AND AT EVERY SECOND SEAT POSITION. REMOVE REDUNDANT 12 OFF PSU PANELS I.A.W. AMM TASK 25-23-61-002-035
- 11 INSTALL NEW INFILL PANELS I.A.W. BOEING 737 AMM TASK 25-23-61-402-026. NOTE: EXISTING INFILL PANELS MAY BE SUBSTITUTED BY SMALLER ITEMS WITH THE SAME TOTAL LENGTH. SELECT ADJUSTMENT PANEL LENGTH TO SUIT INSTALLATION.

**THIS DRAWING IS APPLICABLE TO THE FOLLOWING AIRCRAFT.**

REG No:	MSN:
G-MADA	24919
9H-MAC	24968

ITEM	GRID REF	PART No.	DESCRIPTION	QTY	SUPPLIER	NOTES	ITEM WT
5							
4							
3							
2		960-UA101C-2RMOD	SEAT, RH, BC	14		ALL RH SEATS	
1		960-UA101C-2LMOD	SEAT, LH, BC	14		ALL LH SEATS	
		SA430-00-700-01	56 PAX LOPA				

NEXT HIGHER ASSEMBLY <b>B737-MOD-0022</b>		ALL DIMENSION ARE IN INCHES UNLESS OTHERWISE STATED. TOLERANCES (UNLESS OTHER STATED): .XX ±0.01 .XXX ±0.001 ANGULAR ±½°		ISSUE	DATE	DRN REF	DQN INCORPORATED	DRAWN:	CHECKED:	APPROVED:	TITLE: <b>ORYX B/C SEATING 56 PAX LOPA</b>		
PROJECTION (3RD ANGLE)		SHEET SIZE <b>A0</b>		A	05-01-17		INITIAL ISSUE	NAME:	D.A.HILL	T.TICKNER-HINKES	S.SWIFT	A/C TYPE:	737-548
THIS DOCUMENT CONTAINS PROPRIETARY INFORMATION AND SHALL NOT BE USED OR REPRODUCED, OR ITS CONTENTS DISCLOSED IN WHOLE OR IN PART WITHOUT THE PRIOR WRITTEN CONSENT OF SAI INTERIORS Ltd.		2019		B	27-02-17		FWD SEATING REDUCED FROM 46". NOTES 11 & 12 AMENDED	DATE:	18/09/2019	18/09/2019	18/09/2019	SCALE:	1:20
starlingaerospace aircraft interior solutions		Stewart House, Brook Way, Leatherhead, KT22 7NA www.fly-sai.com +44 1372 378079		C	04-05-17		NOTES REVISED & REFORMATTED.	DRAWING NO: <b>SA885-737-001</b>		1 OF 1 SHEETS		ISSUE <b>F</b> SA-DO-Form.060 ISSUE 4	
				D	21-09-17		MONUMENT STATIONS ADDED. A/C REG'S & MSN No's ADDED.						
				E	18-09-2019		DIM WAS 19.45. DIM WAS 7 PITCHES. DIM 42.00 ADDED						
				F	25-09-2019		DIM WAS 4 PITCHES. STA WAS 391.95. DIMS 44 & 45 ADDED.						